

DELIVERED PROCEDURE FILES TEMPLATE
M3UEHRFBBNDL001

Delivered Procedure Files Template

Payload/Experiment Name Bonner Ball Neutron Detector

Payload POC Cindy Haven

Procedure Developer HRF

Email cynthia.p.haven1@jsc.nasa.gov

Email sondra.fabian@lmco.com

Total Files Submitted 20

Files submitted this delivery 1

The Payload Developer is responsible for the preparation, coordination and maintenance of these procedures. If you have comments or questions about these procedures please contact the Procedure Developer.

Delivery Modified Date	Filename	Procedure Title	Initial Inc Generic	Recovery Plan/Comments
11/21/00	M3UEHRFBBNDL001	Delivered Procedures Files Template	3	Refer to PIMS for latest Inc 2 files list to make comparison to Inc 3 list for any new or deleted files via OCR.
10/13/00	MGUEHRFBBNDN001	BONNER BALL NEUTRON DETECTOR OPERATIONS	2	Refer to PIMS for latest file.
10/13/00	MGUEHRFBBNDN002	BONNER BALL NEUTRON DETECTOR MAINTENANCE	2	Refer to PIMS for latest file.
10/13/00	MGUEHRFBBNDN003	BONNER BALL NEUTRON DETECTOR HARD DRIVE STOW	2	Refer to PIMS for latest file.
10/13/00	MGUEHRFBBNDN004	BONNER BALL NEUTRON DETECTOR POWER OFF AND STOW	2	Refer to PIMS for latest file.
10/13/00	MGUEHRFBBNDN005	BONNER BALL NEUTRON DETECTOR STATUS CHECK	2	Refer to PIMS for latest file.
10/13/00	MGUEHRFBBNDN006	BONNER BALL NEUTRON DETECTOR RELOCATE	2	Refer to PIMS for latest file.
3/28/01	MGUEHRFBBNDA001	BONNER BALL NEUTRON DETECTOR MAINTENANCE -SPECIAL USE	2	New to Inc 2 via OCR hopsall000036. Refer to PIMS for latest file.

DELIVERED PROCEDURE FILES TEMPLATE
M3UEHRFBBNDFL001

Delivery Modified Date	Filename	Procedure Title	Initial Inc Generic	Recovery Plan/Comments	
4/4/01	MGUEHRFBBNDA002	BONNER BALLNEUTRON DETECTOR MAINTENANCE -NO DOWNLINK	2	New to Inc 2 via OCR hopsall000044. Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDR001	Figure 1. Accessory Hardware Placement	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDR002	Figure 2. BBND Installation	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDR003	Figure 3. BBND Hard Drive Insertion	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDR004	Figure 4. Securing HRF Power Converter	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDR005	Figure 5. BBND Deployed Configuration in LAB1D3	2	Refer to PIMS for latest file.	
10/13/00	MGUEHRFBBNDR006	FIGURE 6 BBND CONNECTION BLOCK DIAGRAM	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDVP001	BBND Validation Plan	2	Refer to PIMS for latest file.	
10/13/00	MGUEHRFBBNDVR004	Manual Procedure Validation (PV) Record Report	2	Refer to PIMS for latest file.	
4/4/01	MGUEHRFBBNDVR007	Manual Procedure Validation (PV) Record Report	2	To support BBNDA002. Refer to PIMS for latest file.	
3/28/01	MGUEHRFBBNDVR006	Manual Procedure Validation (PV) Record Report	2	To support BBNDA001. Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDLF001	MPV Links HRF BBND Procedures	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDM001	BONNER BALL NEUTRON DETECTOR LIGHTS OUT	2	Refer to PIMS for latest file.	
9/21/00	MGUEHRFBBNDM002	BONNER BALL NEUTRON DETECTOR MALFUNCTION TABLE	2	Refer to PIMS for latest file.	
9/21/00	BBNDoverview.doc	Untitled	2	Overview information. PODF info only. NOT FOR FLIGHT. In INC2 FINAL wing.	

DELIVERED PROCEDURE FILES TEMPLATE
M3UEHRFBBNDL001

Delivery Modified Date	Filename	Procedure Title	Initial Inc Generic	Recovery Plan/Comments
9/21/00	BBNDsafetygrdcbl.pdf	Untitled	2	Picture of safety ground cable. NOT FOR FLIGHT. In INC 2 FINAL wing.
9/21/00	SGUEHRFBBNDSH001.doc	Procedure Hazard Control List: BBND	2	NOT FOR FLIGHT. In INC 2 FINAL wing.
9/21/00	MGUEHRFBBNDON001			Baselined in Inc.2. Located in INC 2 FINAL wing.